



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: March 10, 2009

Reviewed: 

Mine Name: High Country Rock Co	Permit Number: S/051/0011
Operator Name: Gary Applegate	Inspection Date: 09-17-2008
Inspector(s): L Heppler	Time: 7:00 PM
Other Participants: none	Mine Status: PRO

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


Bond Amount: \$7,000 **Bond Renewal Date** 03/07/2010 **Permit fee:** \$150 due - invoice sent out 06/20/2009

Purpose of Inspection: Routine annual Inspection

Inspection Summary: No concurrent reclamation was evident. No evidence of growth medium salvage or any revegetation efforts. Every effort should be made to growth medium from the site. No trash was noticed on site.

Photos were taken to document site conditions, see attached photos.

Conclusions and Recommendations: OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature 

LAH:vs

cc: Gary Applegate

O:\M051-Wasatch\S0510011-HighCountryRock\inspections\insp-09172008.doc

